
3X220 VAC

THE GRID ON THE VESSEL IS 3X220VAC

INVERTER



TWO WAYS TO REPAIR :

1 - NEW INVERTER 3x220VAC AND REPAIR OF THE PUMP BLOWER

2 - PURCHASE OF THE TRANSFORMER 220/400VAC AND NEW INVERTER

BAD AC MOTOR COOLING SYSTEM

3X220 VAC SHOULD BE 3X400 VAC

THIS MOTORREQUIRES 3X400VAC SUPPLY.

- AFTER REPAIR


MOTOR 2

ORIGINAL COOLING SYSTEM


3X220 VAC

MOTOR 1

BEFORE REPAIR



COOLER FAN



COOLER FAN

BTT Automatyka	REGULATED COOLING SYSTEM FOR DIESEL ENGINE .	cooling system ORIGO 19 XI 2026	Projekt: Andrej	Nr rysunku:	Nazwisko: / Modyfikacja: / Schemat: 1
			Data: 18.11.2026	Funkcja: / Lokalizacja:	Lb. sch: 6 / Sch. nast: 3